

November 27<sup>th</sup> 2018

Notification: End of Life

NIC Products Affected: NTPL series of SMT tantalum chip capacitors

See **EOL** part numbers listed below

Reason for EOL: Reduced demand from market

EOL PN	VOLTAGE RATING	CAP VALUE	CASE SIZE	SUGGESTED REPLACEMENT PN	NOTES
NTPL476M2.5P(150)F	2.5VDC	47uF	P (2012)	NTC-T476M4TRPF	4VDC, ↑ESR, ↓RCR, ↑Height
NTPL107M2.5P(150)F	2.5VDC	100uF	P (2012)		
NTPL686M4P(150)F	4VDC	68uF	P (2012)		
NTPL106M6.3P(250)F	6.3VDC	10uF	P (2012)	NTC-T106M6.3TRPF	↑ESR, ↓RCR ↑Height
NTPL226M6.3P(150)F	6.3VDC	22uF	P (2012)	NTC-T226M6.3TRPF	↑ESR, ↓RCR ↑Height
NTPL476M6.3P(150)F	6.3VDC	47uF	P (2012)		
NTPL157M6B4(100)F	8VDC	150uF	B (3528)		
NTPL475M10P(300)F	10VDC	4.7uF	P (2012)	NTC-T475M10TRPF	↑ESR, ↓RCR ↑Height

Last time order: supporting business from established customers until May 27<sup>th</sup> 2019

Last time delivery: November 27<sup>th</sup> 2019

Sign-up and follow NIC PCN-EOL notices at: <a href="https://www.niccomp.com/pcn/index.php">www.niccomp.com/pcn/index.php</a>